

ERRIS EXECUTIVE SUMMARY

Wang Sequence # _____

WINDSHIELD SURVEY ☒ YES ☐ NOEPA ID# IND980607519Original Company Name: Gertrude Avenue Disposal Facility

Revised Company Name: _____

Alias Names: General Realty; Linden Rd. Dump; Bremen Iron & Metal
Western Ave. Iron and Metal; Schulman Dump; Steve & GenesOriginal Address: 3123 Gertrude AvenueCorrected ☒ South Bend, IN 46613St. Joseph County☒ Landfill ☐ Generator ☐ Treatment, Storage, Disposal (TSD)
☐ Transporter ☐ Other: _____PRIORITY ASSESSMENT: ☐ HIGH ☒ MEDIUM ☐ LOW ☐ NO FURTHER ACTION (NONE)

CLASS:

☐ I-STATE LEAD☒ II-REM/FIT LEAD☐ III-REM/FIT LEAD☐ IV OTHER:

State Accompanies

Limited On-site

FIT

State Involvement

Priority Justification and State Comments Regarding:

☒ PA ☐ SI ☐ Follow-up SI ☐ RPS ☐ HRSThis site (3 contiguous facilities) has allegedly accepted hazardous materials.
Groundwater contamination was documented but results are no longer available.Site characterization is recommended. Soil sampling will prove difficult
because of the materials (scrap) being all over the site.Some trenches and areas indicative of buried material were noted.Solvents have been known to be dumped on the ground.This area is composed of sand and gravel. Continuous clay layers are unlikely.Water table is seasonably high about 6 ft. or less from surface.This apparently was a "Land Reclamation" area permitted by the St. Joseph
County Health Department. Therefore, the State recommends a site inspection
with sampling of groundwater and soil.

STATE INVOLVEMENT

☐ Preliminary Assessments ☐ Site Inspection ☐ Follow-up Site Inspection
☐ Responsible Party Search ☐ Hazard Ranking System (HRS)

* COMPLETE DOCUMENTS (C) REVIEW DOCUMENTS (R)

Prepared by: Mary Anne HunterPhone: (317) 243-5128 Date: 12/6/85Activity Time: 37 Hours

EPA Region 5 Records Ctr.



301543